
YGOSTAR Instructions Isolation gown PROTECT (277461ff)




Classifica-				
Test on whole suits	Outcome	Result	tion	
Seams: strength (EN ISO 13935-2)	Pass	50 < N < 75	Class 2	
Tests on fabric	Outcome	Result	Classifica- tion	
Abrasion Resistance (EN 530 - method 2)	Pass	500 < c < 1000	Class 2	
Trapezoidal tear resistance (EN ISO 9073-4)	Pass	10 < N < 20	Class 1	
Tensile strength (EN ISO 13934-1)	Pass	30 < N < 60	Class 1	
Puncture resistance (EN 863 - EN 13034)	Pass	5 < N < 10	Class 1	
Flex cracking resistance (EN 7854)	Pass	> 100 000 c.	Class 6	
Resistance to penetration by blood-borne phatogens - phi-x174 bacteriophage test - ISO 16603/16604	Pass	20 kPa	Class 6	
Resistance to penetration by infective agents due to mecha- nical contact with substances containing contaminated li- quids - ISO 22610 (test microor- ganism: staphylococcus aureus)	Pass	t > 75	Class 6	
Resistance to penetration by con- taminated liquid aerosols - ISO DIS 22611 (test microorganism: staphylococcus aureus)	Pass	log > 5	Class 3	
Resistance to penetration by contaminated solid particles - EN ISO 22612 (test microorga- nism: spores of Bacillus subtilis)	Pass	log ufc < 1	Class 3	
pH (EN ISO 13688 – ISO 3071)	Pass	3.5>pH>9.5	Pass	
Amines (EN ISO 13688 - ISO 3071)	Pass	-	Pass	
EN ISO 13688:2013	Pass	-	-	
EN 14325:2004	Pass	-	-	

This gown has been tested as a complete suit unit and passed the requirement of following standards: EN ISO 13688:2013, EN 14325:2004 and EN 14126:2003+AC:2004. These are harmonized standards of the EN 340:2003 and of the directive (EU) VO 2016/425 for personal protective equipment.

Fabric: Material protective part (frontal side + sleeves) 100% polypropylene + polyethylene film 40 g/m2 +/- 5% Material non protective part (back side) 100% polypropylene 25 g/m2 +/- 5%

B. Marking:

Each isolation gown is identified with an inside label. This indicates the type of protection offered and other details of information.



- 1 Brand
- 2 Model identification with example article number
- 3 CE marking signifying compliance with PPE of Cat. III according to European legislation.

EN 14126:2003+AC:2004 for protective clothing against infective agents.

4 Size designation as defined in EN ISO 13688:2013, clause 6

Size	Chest circumference	Body height
М	92-112	165-175
L	95-115	170-180
XL	97-117	180-190

5 The symbol informs the wearer to study the instructions for use 6 International care symbols



C. Application and limitations of use

The isolation gown is used as protection cloth against against infectious and biological agents. For details please refer to the performance table.

This product is meant to protect the body. Always check for holes, tears, breach at material or incomplete seams to ensure maximum protection. Do not don the gown if the material is faulty, or if the elastic bands are loose. The knitted ankle cuffs have to be taped with solvent-resistant adhesive strips. Protect uncovered parts of body (hands, respiratory areas, foot) with protective gloves, boots, eventual mask etc. attached to the coverall (if necessary, adding adhesive stripe) and offered the same level of protection in order to provide for full body protection.

The full text of the EU declaration of conformity is available at the following internet address: <u>www.franz-mensch.de</u>

D. The expected shelf life of the garment

The user or supervisor are the ones who can most accurately determine how long a gown can be worn. The expected shelf life of the garment can be more than 5 years if the gown are kept in its original packing in a cool and dry place.

E. Instructions for fitting and removal

<u>To don the gown</u>: First slide your arms through the arm opening. Then pull the gown smooth over the whole body and tie it tightly at the back. <u>To remove the gown</u>: First loosen the tie behind the back, then pull off the sleeves to the front.

F. Usage restrictions

The gown shall not be used in areas where there is a risk to not tested chemicals. The user is the one who defines the suitability of the isolation gown for the required protection level and the correct combination of gown and additional equipment. The isolation gown should be kept away from open flames. The gown is for single use. Do not wash for reuse. The user is advised that prolonged wearing of protective suits may cause heat stress. The gown is made of breathable material in which heat stress should not occur, but the possibility and consequences of heat stress must be considered in very warm conditions. Heat stress can be reduced or provided with appropriate underwear and ventilation.

G. Storage

The isolation gown should be stored in a cool and dry place. Do not store the isolation gown under direct sunlight or close to UV source. Restrictions of disposal depend entirely on any contamination which may have accured during use.

This product has been certified by the notified body

Centro Tessile Cotoniero & Abbigliamento S.p.A. (Centrocot) Piazza Sant'Anna 2 21052 Busto Arsizio (VA) - Italy EEC Notified Body N°0624

This product has been certified (Module B) and it's under control (Module C2) by the notified body.

Franz Mensch is a certified company according to DIN EN ISO 9001:2015